



WELCOME TO THOR™

THOR, powered by Instantel, is a Windows-based software program that interfaces between your computer and your Instantel monitoring unit.

THOR offers powerful, easy-to-use features for event management and compliance reporting. By using THOR, you can program all your Micromate® and Minimate Pro™ devices, manage all the recorded events, and remotely control each unit's monitoring preferences. You can also view and organize all Minimate Plus and Blastmate III units within THOR projects. On top of the mentioned features, you can customize your report content, select your required frequency standards and much more, all right from your Windows computer or laptop.

To enhance the ease of use of our THOR release notes, we have moved the historical THOR release notes and key features section.

To view the THOR key features overview, please [click here](#).
To view all historical THOR release notes, please [click here](#).

Release Notes – THOR™ 1.1.1 - Released August 12, 2019

WHAT'S IMPROVED?

- Updated framework version support: Previous THOR versions required .NET Framework v3.5 to run. THOR will now run on systems with .NET Framework 4.0 and up.
- Resolved an issue where THOR would change the Histogram Interval number to the default number when the Setup File was saved under a new name.
- Resolved an issue where users would not see some or all events in the *Manage Events View* due to a filter being applied on an invisible column. When a column is no longer visible in the *Manage Events View*, all filters for that column will now be removed automatically.
- Resolved an issue where users were unable to accurately set up the Sound Level Microphone with Minimate Pro units affecting the LN2 setting.
- Resolved an issue where users were unable to open and read Micromate event files within THOR that had previously been opened through Blastware v10.74.
- Resolved an issue where during a THOR update, occasionally the Auto Call Home (ACH) service would continue to run and fail to shut down. This would lead to an incomplete THOR/ACH installation since a complete shutdown is required and subsequently, may have led to some units failing to call home.